



Summary

Industry:	Metals
Application:	Factory Effluent Pump
Actual Saving:	£5,000
Payback Period:	14 months



Pump Hose Failure Solved

ERIKS solve pump failure with alternative product

ISSUE

The customer, a large steel producer was using a 4" peristaltic pump to move water and particles of grit. When larger particles got into the pump, the hose would become damaged and had to be replaced, this failure was occurring on a regular basis.

SOLUTION

ERIKS quote the customer a Seepex progressive cavity pump equipped with smart stator. This pump can handle the larger solids and can be easily maintained in line. Also, this design of pump does not use hose, eliminating the customers problem.

OTHER BENEFITS

- Saving on spares usage

FURTHER COMMENTS...

ERIKS extensive supplier network ensured they knew of the best solution for the problem.

MORE INFORMATION

ERIKS Industrial Services

Amber Way, Halesowen,
West Midlands B62 8WG

Tel: 0845 006 6000

Web: www.eriks.co.uk

know-how makes the difference

ERIKS