



Summary



Industry:	Utilities
Application:	Humus tank blades
Actual Saving:	£Undisclosed
Payback Period:	Undisclosed



Settlement tank blades replaced

ERIKS in-house facility meets customer needs

ISSUE

A large Wastewater customer was experiencing frequent problems with scraper blades becoming detached on various settlement tanks. Each time it happened there was disruption to the process which required the tank to be drained for the broken equipment to be recovered and the repairs completed.

SOLUTION

With ERIKS extensive knowledge and historical experience of these issues a local in-house manufacturing facility was set up to turnaround replacement blades and fittings within 48 hours, thus minimising customers downtime.

OTHER BENEFITS

- Fast turnaround minimising downtime
- Further downtime and disruption avoided

FURTHER COMMENTS...

Urgent breakdown fabricated and replaced in 7 days by ERIKS in-house facility and experience application engineers

MORE INFORMATION

ERIKS Industrial Services

Amber Way, Halesowen,
West Midlands B62 8WG

Tel: 0845 006 6000

Web: www.eriks.co.uk

know-how makes the difference

